

Toxicity Characteristic Leaching Procedure (TCLP) Regulatory Levels

METALS	TCLP Regulatory Level, mg/L	EPA Hazardous Waste Number	Recommended Test Method
Arsenic	5.0	D004	7061
Barium	100.0	D005	7080
Cadmium	1.0	D006	7130
Chromium	5.0	D007	7190
Lead	5.0	D008	7420
Mercury	0.2	D009	7471
Selenium	1.0	D010	7741
Silver	5.0	D011	7760

VOLATILE ORGANICS	TCLP Regulatory Level, mg/L	EPA Hazardous Waste Number	Recommended Test Method
Benzene	0.5	D018	8260B
Carbon Tetrachloride	0.5	D019	8260B
Chlorobenzene	100.0	D021	8260B
Chloroform	6.0	D022	8260B
1,4-Dichlorobenzene	7.5	D027	8260B
1,2-Dichloroethane	0.5	D028	8260B
1,1-Dichloroethylene	0.7	D029	8260B
Methyl Ethyl Ketone	200.0	D035	8260B
Tetrachloroethylene	0.7	D039	8260B
Trichloroethylene	0.5	D040	8260B
Vinyl Chloride	0.2	D043	8260B

SEMIVOLATILE ORGANICS	TCLP Regulatory Level, mg/L	EPA Hazardous Waste Number	Recommended Test Method
o-Cresol	¹ 200	D023	8270C
m-Cresol	¹ 200	D024	8270C
p-Cresol	¹ 200	D025	8270C
Cresol	¹ 200	D026	8270C
2,4-Dinitrotoluene	0.13	D030	8270C
Hexachlorobenzene	0.13	D032	8270C
Hexachlorobutadiene	0.5	D033	8270C
Hexachloroethane	3.0	D034	8270C
Nitrobenzene	2.0	D036	8270C
Pentachlorophenol	100.0	D037	8270C
Pyridine	2 5.0	D038	8270C
2,4,5-Trichlorophenol	400.0	D041	8270C
2,4,6-Trichlorophenol	2.0	D042	8270C

¹If Cresols cannot be differentiated, total cresol may be used.

ORGANOCHLORINE PESTICIDES	TCLP Regulatory Level, mg/L	EPA Hazardous Waste Number	Recommended Test Method
Chlordane	0.03	D020	8081A
Endrin	0.02	D012	8081A
Heptachlor (and its Epoxide)	0.008	D031	8081A
Lindane	0.4	D013	8081A
Methoxychlor	10.0	D014	8081A
Toxaphene	0.5	D015	8081A

CHLOROPHENOXY ACID HERBICIDES	TCLP Regulatory Level, mg/L	EPA Hazardous Waste Number	Recommended Test Method
2,4-D	10.0	D016	8150
2,4,5-TP (Silvex)	1.0	D017	8150

Reference: 40 CFR 261, Appendix II, 1993 ed., as amended by 58 FR 46040, August 31, 1993.